


FIG. A : XP-3 FLUX-VAC MOUNTED TO LINCOLN WELDING EQUIPMENT



RECOMMENDED SYSTEM ORDER LIST :

- 1) XP-3 FLUX-VAC ; INCLUDED WITH XP-3 AT NO EXTRA COST :
  - A) 4 FT. 1 1/2" FLUX RECOVERY HOSE .
  - B) FLUX PICK-UP NOZZLE (NZ-1) .
  - C) HOPPER SIGHT WINDOWS (2) .
- 2) OPT IONAL HOSE MOUNTING BRACKETS :
  - FHM-1 (LINEAR ADJUSTMENT ONLY)
  - FHM-1ADJ (LINEAR AND ANGULAR ADJUSTMENT) .
- 3) OPT IONAL FLUX PICK-UP NOZZLES :
  - NZ-1CRN CORNER NOZZLE ,
  - NZ-1BUTT BUTT NOZZLE .
- 4) OPT IONAL AV-4 ELECTRIC (115VAC) AIR VALVE . OTHER VOLTAGES AVAILABLE .
- 5) OPT IONAL FF-3 FLUX FEED PIPE . AUTOMATICALLY KEEPS HOPPER FULL OF FLUX . SPECIFY FEED HOSE I.D. , 1/2 , 3/4 , OR 1" (NEED PT-x00 OR SIMILAR FEED TANK) .
- 6) OPT IONAL PT-x00 FLUX FEED TANK (AVAILABLE IN 100LB. , 300LB. , 600LB. , OR LARGER SIZES) .
- 7) OPT IONAL FLUX FEED HOSE . (SPECIFY 1/2 , 3/4 , OR 1" I.D. SIZE) .
- 8) OPT IONAL DC-30 DUST COLLECTOR USED IN PLACE OF DUST BAG FOR GREATER CAPACITY AND LESS MAINTENANCE .

BULLET IN : TB-394  
 FILE : XP3-TB.CAD  
 7/1/98